The Leatherman-Dutrow Farmstead is an agricultural complex now currently a private residence, which retains the major elements of a late 19th century farmstead with alterations to certain structures in connection with agricultural development. The main dwelling house is a two-story frame house with a side wing fronted by a two-story porch. The entry porch in the main section is ornamented by brackets and dentil moldings. The window frames are also molded with pediment lintels. The house is accompanied by a two-level stone and frame springhouse, which may pre-date the house, a frame summer kitchen, a privy, and a chicken house, all of the period 1875-1900. agricultural group has a late 1930's frame bank barn, which shows concrete block alterations and an additional milk house to exemplify the change from grain production to dairying in the early 20th century. A frame wagon shed/corn crib of the last quarter of the 19th century is also part of the group. The house was probably built contemporary with the purchase of the farm by Peter Leatherman (see F-4-32) as one of several farms he owned during the late 19th century. Sold to Henry Dutrow in 1915, it was purchased by the current owner's father, Clarence Koogle, in 1937.

F-4-2233 Leatherman Dutrow Peter Leatherman Farmstead Middletown Frederick County

### HISTORIC CONTEXT:

### MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Piedmont

(Harford, Baltimore, Carroll, Frederick, Howard, Montgomery

Counties, and Baltimore City)

Chronological/Development Period:

Agricultural-Industrial Transition A.D. 1815-1870

Industrial Urban Dominance A.D. 1870-1930

Prehistoric/Historic Period Themes

Agriculture

Architecture, Landscape Architecture and Community Planning

Resource Types:

Category: Building

Historic Environment: Rural

Historic Function and Use:

Domestic/single dwelling/residence Domestic/secondary structure/kitchen

Domestic/secondary structure/garage

Agriculture/subsistence/animal facility/barn

Agriculture/subsistence/storage/granary

Known Design Source: None

## Maryland Historical Trust State Historic Sites Inventory Form

Survey	No.	F-4-33
--------	-----	--------

Magi No.

DOE	yes	no

1. Nam	<b>e</b> (indicate pr	eferred name)		
historic	Leatherman-Dutrow	Farmstead		
and/or common				
2. Loca	ation			
street & number	2902 Station F	Road		not for publication
city, t <b>own</b>	Middletown	X vicinity of	congressional district	6th
state	Maryland	county	Frederick	
3. Clas	sification			
Category  district  X building(s)  structure  site  object	Ownership public private both Public Acquisition in process being considered not applicable	Status  X occupied  unoccupied  work in progress Accessible X yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	and mailing address	ses of <u>all</u> owners)
name Mr.	and Mrs. Grayson [	). Koogle		
street & number	2902 Station Ro	oad	telephone	no.:
city, town Mid	dletown	state	and zip code	ld. 21769
5. Loca	ation of Leg	al Descripti	on	
courthouse, regis	stry of deeds, etc.	rederick County Cou	rthouse	liber 1187
street & number	100 W. Patrick	Street		folio 745
city, t <b>own</b>	rederick		state	Md. 21701
6. Repi	resentation	in Existing	Historical Sur	rveys
title Pai	ul Brinkman Survey	of Frederick Count	y #F-1130	
date C.	1968		federalX s	tate county loca
pository for su	rvey records Md. St	IPO	-	
city, town (	Crownsville		state	∍ Md.

# 7. Description Condition excellent deteriorated Survey No. F-4-33 Check one X original site

\_\_\_ moved

date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

X altered

CONTRIBUTING RESOURCE COUNT: 11

\_\_\_\_ ruins

\_\_\_ unexposed

\_X\_ good

\_\_\_\_ fair

The Leatherman-Dutrow Farmstead is an agricultural complex containing both domestic and agricultural building groups centered on a circa 1875-1880 frame two-story dwelling, with a frame summer kitchen, a two-level stone and frame springhouse, a frame privy, and a frame chicken house. The agricultural group contains a late 1930's frame bank barn with concrete block alterations for dairy operation, a concrete block milk house, a terra cotta silo, a concrete silo, and a frame pump house, all of the same period as the barn, and a frame wagon shed/corn crib of about 1875-1900. The farmstead is located on the north side of Station Road, about 1/4 mile from the intersection of Mount Tabor Road near Middletown, Frederick County, Maryland. The farmstead is reached by a farm lane from Station Road which crosses a small stream running northwest to southeast through the property.

The dwelling has a two-bay, two story main section with a side-by-side wing on The wing has a two-level open porch. The exterior covered with the east side. The two-bay western section has an entry porch with decorative german siding. brackets and dentil molding. The doorway has a plain transom and a four-panel The windows are 2/2 with molded peaked lintels and shaped jambs flanked by Some windows in the house have been replaced with 1/1 modern louvred shutters. The gable roof is covered with corrugated metal and an interior chimney located on the west end and at the junction of the main section and the wing. The west elevation has two bays with two square 2/2 attic windows and 2/2 windows on the first and second stories. The wing has five bays, with two entrances in the inner bay, and an enclosed end bay on the east end. The north elevation of the house has functionally placed windows in irregular bays. A rear entrance is located near the The interior of the house has been considerably altered in terms northeast corner. of wall and floor finishes, but at least one original mantel with molded geometric panels is located in the center room of the three main rooms of the first floor.

#### Domestic outbuildings:

Summer kitchen: The one-story frame summer kitchen is located immediately north of the northeast corner of the dwelling. It has german siding, a corrugated metal gable roof, and a vertical board door on the south elevation. The west elevation has two square windows with vertical muntins, probably replacing the original sash, which was presumably 2/2 as in the main house. The summer kitchen was probably built at the same time as the house, approximately 1875-1880.

Springhouse: The two-story stone and frame springhouse is located near the creek south of the dwelling. According to Mr. Koogle, the current owner, an earlier house stood on the property near the springhouse. The springhouse may therefore be older that the rest of the buildings in the present farmstead, possibly 1850 to 1870. The generally rectangular building has a stone lower level and german siding on the frame upper level. The building is deteriorated and the original shingle roof is partially visible under corrugated metal. An exterior stone and brick chimney in

(Continued on separate sheet)

1600–1699 1700–1799 _X1800–1899	.,	• •	literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	C. 1875-1940	Builder/Architect	· · · · · · · · · · · · · · · · · · ·	
a: Appl	icable Criteria: XA nd/or icable Exception:A  l of Significance:	A _B _C _D1		

F-4-33

Survey No.

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Leatherman-Dutrow Farmstead is a good example of the late 19th century farm grouping, showing the typical types of structures in use in both domestic and agricultural areas, and the changes which took place as improvements in home life and farm operation were made in the early 20th century. The dwelling house shows the persistence of vernacular architectural traditions based in the second quarter of the 19th century in the window and door trim and the plan of the house with the side wing. The springhouse, a surviving element common to most 19th century farms, is now abandoned, as a modern well provides water to the complex. The privy and chicken house, both essentials in the late 19th century, are superceded by modern plumbing and food supplies from other sources than the farm itself. agricultural group has a bank barn, silos, a milk house, and a wagon shed/corn crib, all common elements in a working farm of the period, which are no longer used because the farm is currently a private residence. The sequence of active agricultural use followed by conversion to residential use is repeated throughout the Middletown Valley. The Peter Leatherman Farmstead (F-4-32) is a similar example.

The farm was part of the holdings of Peter Leatherman, who probably established the farm as a tenant holding, although the house and some of the outbuildings may have been built prior to his acquisition in 1880. Henry Dutrow owned the farm from 1915 to 1937 and Clarence D. Koogle, father of the present owner, acquired the property in 1937. The barn was built by Mr. Koogle.

## **Major Bibliographical References**

Survey No. F-4-33

Land Records of Frederick County Koogle, Mr. & Mrs. Grayson D., personal interview, Feb. 20, 1992

10. Ge	ographical Data		
Acreage of nom Quadrangle nar UTM References		nces	Quadrangle scale 1:24000
A Zone East		B	ng Northing
C		D	
	ary description and justification ely 3 acres centered on the h	ouse and outbuildi	ings on Tax Map 54,
List all states	and counties for properties overlap	pping state or county	boundaries
state	code	county	code
state	code	county	code
11. Fo	rm Prepared By		
name/title	Janet L. Davis, Historic Sit	es Surveyor	
organization	Frederick County Planning &	Zoning Dept <sub>date</sub>	March, 1992
street & number	12 E. Church Street	telephon	e 696-2958
city or town	Frederick	state	Md. 21701

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HIS ICRUAL TRUE DHCP/DHCD 100 COMMUNITY PLACE CROWNSVILLE, MD 21032-2023

-514-7600

Leatherman Duthon tarmstead

Peter Leatherman Farmstead

Frederick County

### 7.1 Description (Continued)

located on the south gable end and a single 6/6 window is located in both the east and west elevations. A 6-panel door to the lower level is in the east elevation. A vertical board door to the upper level as well as a second lower level entrance are located in the north gable end. The spring itself is visible near the northwest corner of the building, with an intake opening in the stone foundation to the interior trough.

Privy: The square frame privy stands northeast of the house on the north side of the driveway. This may be a relocation of the structure. Built probably about the same time as the house, it has a shed corrugated metal roof and vertical board siding. A vertical board door in on the south elevation.

Chicken house: The frame chicken house is a deteriorated structure located on the south side of the driveway, east of the dwelling. Its date may be in the last quarter of the 19th century. It has vertical board siding, and a corrugated metal shed roof, with the window openings, mostly without sash, on the south elevation.

Agricultural outbuildings (no longer in active use):


Barn and terra cotta silo: The late 1930's frame bank barn probably replaced an earlier barn on the same location. It has the ramp on the north elevation flanked by a terra cotta tile silo with a brick top. The barn exterior is vertical boards and the gable roof is corrugated metal. The south elevation is partially enclosed with concrete block, forming a milking parlor, and the rest of the lower level is enclosed with tongue-and-groove siding. A corrugated metal loafing shed extends from the southwest corner.


Milk house and concrete silo: The concrete block milk house is a rectangular, one-story building located east of the barn. Built approximately in the late 1930's, it has a corrugated metal gable roof and a vertical board door in the west elevation.

Wagon shed/corn crib: The circa 1875 frame wagon shed/corn crib is located northwest of the barn. It has a single drive-through bay with vertical board siding and a corrugated metal roof. An additional side shed for tools is located on the east elevation.

Pump house: The frame pump house, built approximately in the late 1930's to pump water to the milk processing operation in the barn, is located on the west side of the driveway south of the wagon shed. It is a rectangular structure with german siding and a corrugated metal gable roof. Two vertical tongue-and-groove doors are located in the north elevation.

#119 2402×	tation Rd.				
LIBER/FCO	GRANTEE	GRANTOR	ORIGINAL TRACTS	COST	DATE
1187/745 13 Dec 82	Drayson D. + Euelyn St. Koogle	Graysun D. Koogle	95 a. "Leatherman Farm"		
615/201 12 Mar 59	Grayson D. Koogle	des.			
409/504 18 Nov 37	Clarence D. 4 anna E. Koogle	Henry C Dutios	"Benjamin's Inbent 950		
	S. Dution	of Peter Paper 01)	"Benjamin's Inheritance" 950.		·
AF2/207 5 June 1880	Deter Leathernan	Dawson & Elizabeth Flook, et al	"Benjamins Inheritarie"	#6500	
CM 1/528 4 apr 1868	Joshua V. Flock	Matthias & Phele	"Benjamin's Inheritance"	#7,5 <b>95</b>	
					7
		·			4-33







E 3" 72





District the tone Falingen y long



f, la la la



F. W. E. 2 February May



J 2 2 Le rella Lancon Dela co Frignes de s-Tillerck Condy Plate Trust Wis File / Mar